




—



Screw the mounting brackets (5) to the surface.




Drill a hole for the power cord in the PDS-4-PLUS extrusion (1).




Mount the gland (7) and run the power cord through the drilled hole.

Insert the 8-KLIK sleeve (3) into the extrusion.



Attach the end caps (2) and the cover.



Connect the power and insert the lighting fixture into the mounting brackets.

LED strip must be connected to a 12 V or 24 V power supply.